

BAD BOY

Part # 4713090

- Spindle assembly
 - Fits models 2004 and up
 - Long shaft
- Replaces **Bad Boy 037-6018-00**
\$99.83



Part # 4713089

- Spindle assembly
 - Fits CZT models 2010-2012
 - Old style
- Replaces **Bad Boy 037-6015-00, 037-6015-50**
\$99.83



BOBCAT/BUNTON

Part # P82016

- Spindle assembly
 - Fits ZT223 with 52" decks
 - RH and LH sides
- Replaces **Bobcat/Bunton 2720759**
\$56.94




Part # P82307

- Spindle assembly
- Replaces **Bobcat 36082N**
\$79.50




Part # P82018

- Spindle assembly
 - Fits ZT223 with 52" deck
 - Center spindle
- Replaces **Bobcat/Bunton 2702758**
\$60.44



Part # P82017

- Spindle assembly
 - Fits ZT223 with 61" deck
 - Center spindle
- Replaces **Bobcat/Bunton 2186207**
\$60.44




BOBCAT/BUNTON continued

Part # P82019

- Spindle assembly
- Fits ZT223 with 61" deck
- RH and LH sides

Replaces **Bobcat/Bunton 2186205**

\$60.44




Part # P82320

- Spindle assembly
- For 36" and 48" XM series mowers
- 6-1/4" shaft
- 1" shaft dia.

Replaces **Bobcat 36567**

\$102.60




Part # P82308

- Spindle assembly
- 6-1/2" shaft
- Short hub
- Fits 36", 40", 48", 52" and 61" decks

Replaces **Bunton PAL0806A, J Deere PT8633**

\$83.29




DIXIE CHOPPER

Part # P82322

- Spindle assembly - short shaft
- Fits 50 & 60" rider
- Outside spindle

Replaces **Dixie Chopper 10161**

\$71.38



Part # P82324

- Spindle shaft - short
- For spindle assembly P82322
- 1" diameter shaft

Replaces **Dixie Chopper 30217**

\$56.54




Part # P82323

- Spindle assembly - long shaft
- Fits 50" & 60" rider
- Center spindle

Replaces **Dixie Chopper 10161-L**

\$74.18



DIXIE CHOPPER continued

Part # P82326

- Spindle shaft - long
 - For spindle assembly P82323
- Replaces **Dixie Chopper 30217-L**


\$57.16



Part # P82327

- Spindle housing only
 - For P82323 and P82322
- Replaces **Dixie Chopper 30241**

\$54.30



Part # SA12808

- Spindle Assembly
 - Spindle housing with bearings, seals, long shaft
- Replaces **Dixie Chopper 300442**

\$117.48



Part # SA12806

- Spindle housing
 - With bearings and seals
- Replaces **Dixie Chopper 300440**

\$55.68



Part # SA12807

- Spindle Assembly
 - Spindle housing with bearings, seals, short shaft
- Replaces **Dixie Chopper 300441**

\$116.07



Part # SA10177

- Spindle Housing
 - Fits "Zero Turn" riding mowers
- Replaces **Dixie Chopper 30241**

\$50.40



ENCORE

Part # P82329

- Spindle assembly
- For 48", 52" and 60" decks
- Overall height: 7-1/2"
- 12 splines
- 3/4-16 thread

Replaces **Encore 363379**

\$163.13



Part # P82330

- Spindle assembly
- Fits ZS and FC models
- For 42", 48", 52" and 61" cut decks
- Overall height: 6"
- 12 splines, 3/4-16 thread

Replaces **Encore 583106**

\$59.54




EXCEL

Part # P82021

- Spindle assembly
- Fits Super Z with 52", 60", 72" decks
- Cast iron housing

Replaces **Excel 350595**

\$56.47



Part # P82335

- Spindle assembly
- Fits FasTrak, Mini-Z and Super Mini-Z

Replaces **Excel 783506**

\$99.60



EXMARK

Part # P82316

- Spindle assembly with short shaft
- Fits 32" and 36" decks
- Fits 48" deck - outside spindles
- 5-1/8" shaft length

Replaces **Exmark 302030**

\$124.41



Part # P82317

- Spindle assembly with long shaft
- Fits 48" deck with long shaft
- Center spindle
- 5-3/4" shaft length

Replaces **Exmark 402006**


\$124.41



EXMARK continued

Part # P82344

- Spindle assembly
 - Fits 48", 52" & 60" Lazer Z HP
- Replaces **Exmark 103-1140**
\$85.81




Part # P82345

- Spindle assembly
 - Fits 52" Lazer Z HP
- Replaces **Exmark 103-1184**
\$107.33




Part # P82347

- Spindle assembly
 - Fits 60" Lazer Z XP series
- Replaces **Exmark 103-3200**
\$85.82




Part # EX13130

- Spindle assembly
 - Fits 48" decks on Lazer Z HP models
- Replaces **Exmark 103-1140**
\$82.00




Part # P82348

- Spindle assembly
 - Fits 72" Lazer Z XP series models
 - Serial number 252,000 and up
- Replaces **Exmark 103-3206**
\$85.82



Part # P82349

- Spindle assembly
 - Fits 72" Lazer Z models
- Replaces **Exmark 644092**
\$91.13



EXMARK continued

Part # P82022

- Spindle housing assembly
- Includes bearings
- Fits Lazer Z, Metro, Viking, Turf Tracer and Turf Ranger
- Pulley and shaft not included

Replaces **Exmark 103-2547**

\$35.00




Part # P82362

- Spindle assembly
- Fits Lazer CT, Lazer HP with serial #'s above 540,000

Replaces **Exmark 103-9081**

\$128.53




Part # P82361

- Spindle assembly
- Fits Lazer Z and Lazer HP with serial #'s above 600,000

Replaces **Exmark 109-2102**

\$116.20



Part # P82056

- Spindle housing
- Fits Lazer XS air cooled (S/N 790,000 & up)
- Lazer Z AC
- Lazer Z XS liquid cooled (S/N 600,000 & up)
- LZDS902K, LZD25KD605, LZDKD725, LZS29PKA606, LZX23KC486, LZX23KC486, LZX24KA526, LZX27KC606, LZX29EKC606, LZX29KA606, LZX34KC606, LZX34KC726, LZX38KC606, LZX34KC726, LZX38KC606, LZX38KC726 (S/N 920,000 & up), LZX801KA606, LZX740KC526, LZX740KC606, LZX980KC726, LZX980KC606, LZX940KC606, LZX749EKC606, LZX680KC486 (S/N 312,000,000 & up), LZX980EKC726 (S/N 313,000,000 & up), & Next Lazer Z Air Cooled (S/N 850,000 & up)

Replaces **Exmark 103-9539**

\$67.27



Part # P82055

- Spindle assembly
- Fits Lazer XS air cooled (S/N 790,000 & up)
- LZDS902K, LZD25KD605, LZDKD725, LZS29PKA606, LZX23KC486, LZX24KA526, LZX27KC526, LZX27KC606, LZX29EKC606, LZX29KA606, LZX34KC606, LZX34KC726, LZX38KC606, LZX34KC726, LZX38KC606, LZX38KC726 (S/N 920,000 & up), LZX801KA606, LZX740KC526, LZX740KC606, LZX980KC726, LZX980KC606, LZX940KC606, LZX749EKC606, LZX980KC486, (S/N 312,000,000 & up), LZX980EKC726 (S/N 313,000,000 & up), & Next Lazer Z Air Cooled (S/N 850,000 & up)

Replaces **Exmark 109-6917**


\$97.60



GRASSHOPPER


Part # P82351

- Spindle assembly
 - Fits 52" and 61" models 9852 & 9861
 - Right and left spindles
- Replaces **Grasshopper 623781, 623763**
\$80.46



Part # P82352

- Spindle assembly
 - Fits 52" and 61" models 9652 and 9661
 - Center assembly
- Replaces **Grasshopper 623782**
\$84.48



Part # P14351

- Spindle assembly
 - Fits 52" and 61" M1-52 and M-61 decks
 - Right and left
- Replaces **Grasshopper 623780**
\$89.04



Part # P14357

- Spindle assembly
 - Fits 48", 52" Cut M1 decks
- Replaces **Grasshopper 623761**
\$89.04



Part # P14358

- Spindle assembly
 - Fits 41", 48", 52" cut M-48 decks
- Replaces **Grasshopper 623760**
\$84.64



GRAVELY

Part # P82040


- Fits ZT series riders
- Replaces **Gravelly 51510000**
\$52.66



GRAVELY continued


Part # P82041

- Outer spindle assembly fits PM series riders
- Replaces Gravelly 59201000
\$72.77



Part # P82042


- Center spindle assembly fits PM series riders
- Replaces Gravelly 59202600
\$78.10



GREAT DANE

Part # P82328

- Spindle assembly
- Replaces Great Dane D18030
\$118.01



Part # P85030

- Spindle shaft
 - For our part # P83328
- Replaces Great Dane D18048
\$47.65



Part # SA12778

- Spindle assembly
 - Fits latest models
 - New heavy duty style with mounting studs
- Replaces Great Dane 200262
\$59.20



HUSTLER

Part # SA11452

- Spindle assembly
 - Fits FasTrak, Mini Z and Super Mini Z models
- Replaces Excel/Hustler 783506
\$65.56



HUSTLER continued

Part # SA12459

- Spindle assembly
 - Fits Super Z with 52", 60" and 72" decks
 - Cast iron housing
- Replaces **Hustler 796235**

\$82.00



Part # P14036

- Housing
- Cast iron spindle housing
- Fits our SA12459
- Replaces **Hustler 034843**

\$39.94



Part # SA12491

- Spindle shaft
- Fits Super Z with 52", 60" and 72" decks
- Replaces **Hustler 796227**

\$29.22



Part # SA12241

- Spindle assembly
 - Fits Super Z with 52", 60" and 72" decks
 - Cast iron housing
- Replaces **Hustler 350595**

\$58.06



Part # SA12833

- Spindle shaft
 - Fits Super Z with 52", 60" and 72" decks
- Replaces **Hustler 788547**

\$27.31



JOHN DEERE

Part # 4714168

- Spindle assembly
- Fits 48" and 60" mower decks for F620, F680 and F687 Z-Trak mowers
- F687 48" and 54" decks for 1420, 145, 1445, 1545, 1565
- F725, 777, 797 60" and 72" decks
- 737, 757, 54" and 60" decks
- 717A, 727A 48" and 54" decks
- Replaces **John Deere TCA13807**

\$89.00



JOHN DEERE continued


Part # JD13385

- Spindle assembly
 - Fits Z-TRAK mowers
- Replaces **John Deere TCA17517**
\$94.36



Part # JD12495

- Spindle assembly
 - For LA150 and LA175, G110, 190C mowers with 54" deck
 - 7 point spline
- Replaces **John Deere GY21099, TY20867**
\$36.23



Part # JD12910

- Spindle assembly
 - Fits LA100 - LA165 series mowers since 2006
 - 7 point spline
 - Used on 42", 48", 54" decks
- Replaces **John Deere GY21098, GY20454, GY20962**
\$38.35



Part # JD13234

- Spindle housing assembly
 - Fits EZ-TRAK
 - Fits models X300, X300R, X304, Z225 and Z245
- Replaces **John Deere AM136733**
\$41.16



MTD

Part # P82051


- Spindle Assembly
 - Fits models 13AR608G, 13AT604G, 13AX604G (1999), 13AD604G (1999-2000), 13A1762F, 13AH762F, 13AM762F (2006), 13A0616G, LT-1650 (2000-2001), ZT-17, 17AA5A4G (2004), 17BA554G, 13A1760F, 13A3760F, 13AM771F (2005), 13AC762F, 13AH762F, 13AM762F (2005-2006), 13AG619H, 13AU618H, 13BR609G (2000), ZT-42 (2005-2008), 13A1762F, 13A3762F, 17AA554G, (2006) & 17AA5AAG (2008)
 - For star center hole blades
- Replaces **MTD 918-4197A, 918-04197, 918-0427, 918-0427A, 918-0427C, 918-0427D, 918-0324, 618-0427D, 618-0427C, 618-0427A, 618-04197A, 618-0324A**
\$44.56



SCAG


Part # P82325

- Spindle assembly
 - Fits all Scag mowers using cast iron spindle assemblies
- Replaces **Scag 46631**
\$55.22



Part # P82309

- Spindle assembly
- Replaces **Scag 46020; Ferris 1530301; Encore 71460007; Wright Stander**
\$99.91



Part # P14081

- Spindle Assembly
 - Fits Freedom Z 36", 48" and 52" decks
- Replaces **Scag 461950**
\$68.67



TORO

Part # 4714122

- Spindle assembly
 - Fits TimeCutter Z
 - Models 74330-74339, 74820, Z5060 and ZX5000
 - Short Shaft
- Replaces **Toro 88-4510 housing;**
117-1192 with shaft (110-6866 old P/N),
80-4380 spacer and 80-4630 shield
\$65.00



Part # 4714121

- Spindle assembly
 - Fits TimeCutter Z
 - Models 71180-71428, 74301-74403
 - Long shaft
- Replaces **Toro 88-4510 housing with bearings,**
80-4341 shaft, 80-4380 spacer
\$69.00



Part # 4713620

- Spindle assembly
 - Fits Toro 62 Z center spindle
 - Use with our part # 4713621
- Replaces **Toro 105-1688**
\$136.20



Part # 4713621

- Spindle assembly
- Fits Toro 62 Z right hand and left hand spindle
- Fits our part # 4713620

Replaces Toro 99-4640

\$115.00




Part # P82675

- Center spindle assembly
- Fits 62" Z models, center

Replaces Toro 105-1688

\$130.34




Part # P82674

- Spindle assembly
- Fits 52" Z models

Replaces Toro 100-3976

\$113.43



Part # P82676

- Outer spindle assembly
- Fits 62" Z models

Replaces Toro 99-4640

\$106.35



Part # P14132

- Spindle housing with bearings and spacer

Replaces Toro 107-9161

\$31.04



WRIGHT

Part # P82309

- Spindle assembly
- Replaces **Wright 71460007**
\$99.91



Part # P14282

- Spindle assembly
 - Fits 32", 36" and 42" decks
- Replaces **Wright 71460022**
\$90.45



POP Parts APP

- The fastest way to order frequently used parts
- Use the app to order by bar code
- Just scan the bar code printed on your order confirmation or online at performanceoutdoorproducts.com
- Enter your quantities (or access your history for previous quantities)
- Submit your order
- Contact us with questions

